



# Diffusion studies

Diffusion are key issues to study when treatments are applied to samples. The following example features a Cu layer on stainless steel before and after heat treatment. Only a zoom on the minor elements is proposed.

The effect of the treatment is a migration of several elements from the stainless steel to the surface Cu layer which changes drastically the properties of the material. GD can study easily these processes and help in controlling them accurately.

